DEC. 17. 2003 6:35PM MEDTRONIC LAW DEPT

Applicants: Rutten et al. Serial No.: 09/934,189

Page 19

## AMENDMENTS TO THE DRAWINGS

NO. 8561

P. 22/27

The attached replacement sheet includes changes to FIG. 3. This sheet, which includes changes to re-number inadvertently mislabeled reference numeral "56", indicating a distal attachment point for attaching the pull wire 50 at the distal segment 20, as described at page 13, lines 17-21, for example, to reference numeral "58". No;new matter has been added.



